

SA's Leading Past Year

Exam Paper Portal



You have Downloaded, yet Another Great
Resource to assist you with your Studies 😊

Thank You for Supporting SA Exam Papers

Your Leading Past Year Exam Paper Resource Portal

Visit us @ www.saexampapers.co.za



SA EXAM
PAPERS



basic education

Department:
Basic Education
REPUBLIC OF SOUTH AFRICA

NATIONAL SENIOR CERTIFICATE

GRADE 12

MECHANICAL TECHNOLOGY

FEBRUARY/MARCH 2016

MEMORANDUM

MARKS: 200

This memorandum consists of 18 pages.

QUESTION 1: MULTIPLE-CHOICE QUESTIONS

- | | | |
|------|-----|-------------|
| 1.1 | C ✓ | (1) |
| 1.2 | B ✓ | (1) |
| 1.3 | D ✓ | (1) |
| 1.4 | D ✓ | (1) |
| 1.5 | A ✓ | (1) |
| 1.6 | C ✓ | (1) |
| 1.7 | D ✓ | (1) |
| 1.8 | D ✓ | (1) |
| 1.9 | B ✓ | (1) |
| 1.10 | D ✓ | (1) |
| 1.11 | D ✓ | (1) |
| 1.12 | C ✓ | (1) |
| 1.13 | B ✓ | (1) |
| 1.14 | B ✓ | (1) |
| 1.15 | A ✓ | (1) |
| 1.16 | C ✓ | (1) |
| 1.17 | A ✓ | (1) |
| 1.18 | C ✓ | (1) |
| 1.19 | D ✓ | (1) |
| 1.20 | B ✓ | (1) |
| | | [20] |

QUESTION 2: SAFETY**2.1 Safety – Centre lathe**

- Look out for revolving work pieces ✓
- Do not remove shavings by hand ✓
- Be careful not to run the cutting tool into the chuck ✓
- Do not make any adjustments on the work piece while the machine is running ✓
- Do not leave tools on the machine while in operation ✓

(Any 2 x 1) (2)

2.2 Safety – Tensile Tester

- Use safety goggles ✓
- Do not apply excessive pressure ✓
- Test piece to be well secured for testing ✓
- Check hydraulic fluid level ✓

(Any 2 x 1) (2)

2.3 Safety – Spring Tester

- Spring tester should be in a good condition ✓
- Spring tester must be fitted correctly and firmly ✓
- Ensure that the spring cannot slip out of position before applying the load ✓
- An uniform load must be applied ✓
- Release the load carefully and uniformly ✓

(Any 2 x 1) (2)

2.4 Safety – Cylinder Leakage

- Clean the area around the spark plug, before removing the spark plug ✓
 - To prevent dirt from falling into the cylinder. ✓
- Be careful when removing radiator cap ✓
 - The water may be hot and under pressure. ✓
- Do not exceed the specified pressure to test the cylinder ✓
 - To prevent damage to the seals and tester. ✓
- The tester must fit properly and be well tightened in the spark hole or injector hole ✓
 - To prevent damage to the tester and spark hole or injector hole. ✓

Any 2 x 2 (4)
[10]

QUESTION 3: TOOLS AND EQUIPMENT**3.1 Compression testing**

- 3.1.1
- Wet compression test ✓
 - Dry compression test ✓
- (2)

- 3.1.2
- Worn cylinders ✓
 - Worn piston rings ✓
 - Worn piston ✓
 - Leaking inlet valve ✓
 - Leaking exhaust valve ✓
 - Leaking cylinder head gasket ✓

(Any 2 x 1) (2)

3.2 Oil pump

- Oil pressure meter or oil pressure tester ✓
- (1)

3.3 Cooling system test

- Remove the radiator cap and fit the tester ✓
- Pump air at the prescribed pressure into the system ✓
- Note the reading ✓ and if the reading drops, it indicates a leaking system ✓
- To test for a leaking cylinder-head gasket, ✓ the engine is started. ✓
- If the reading increases while the engine idles, it indicates on a leaking cylinder-head gasket ✓

(7)
[12]

QUESTION 4: MATERIALS**4.1 Iron-carbon properties****4.1.1 Pearlite:**

- Good ductility ✓
- Hard ✓
- Strong and tough ✓
- Resistant to deformation ✓

(Any 2 x 1) (2)**4.1.2 Cementite:**

- Intensely hard ✓
- Brittle. ✓

(2)

4.2 Critical points**4.2.1 AC₁ – lower critical point**

- The lowest temperature to which steel must be heated to be hardened. ✓✓
- The lowest temperature where the structure starts to change. ✓✓

(Any 1 x 2) (2)**4.2.2 AC₃ – high critical point**

- The highest temperature to which the steel can be heated to obtain maximum hardness. ✓✓
- The temperature where the steel completely loses its magnetic properties. ✓✓
- The temperature where the steel's structure is at its finest. ✓✓

(Any 1 x 2) (2)

4.3 Carbon content determines the hardness of steel. ✓ (1)

4.4 Cementite structure in steel determines the hardness. ✓ (1)

4.5 Ferrite structure in steel determines the ductility. ✓ (1)

4.6 Austenite is a solid solution of iron and carbon also called iron carbide. ✓
The structure is at its finest. ✓ (2)

[13]

QUESTION 5: TERMINOLOGY**5.1 Gear calculation**

- 5.1.1 Circular pitch = $m \times \pi$

$$\text{module} = \frac{\text{circular pitch}}{\pi}$$

$$= \frac{12,567}{\pi}$$

$$= 4 \text{ mm}$$

✓
✓
✓
(3)
- 5.1.2 Outside diameter = $\text{PCD} + 2m$
 $\text{PCD} = \text{OD} - 2m$
 $= 112 - 2(4)$
 $= 104 \text{ mm}$

✓
✓
✓
(3)
- 5.1.3 CuttingDepth = $2,157m$
 CuttingDepth = $2,157 \times 4$
 $= 8,628 \text{ mm}$
 $= 8,63 \text{ mm}$
 OR
 CuttingDepth = $2,25m$
 CuttingDepth = $2,25 \times 4$
 $= 9 \text{ mm}$

✓
✓
(2)
- 5.1.4 Addendum = m
 $= 4 \text{ mm}$

✓
(1)
- 5.1.5 Dedendum = $1,157m$
 $= 1,157 \times 4$
 $= 4,628 \text{ mm}$
 $= 4,63 \text{ mm}$
 OR
 Dedendum = $1,25m$
 Dedendum = $1,25 \times 4$
 $= 5 \text{ mm}$

✓
✓
(2)
- 5.1.6 Clearance = $0,157m$
 $= 0,157 \times 4$
 $= 0,628 \text{ mm}$
 $= 0,63 \text{ mm}$
 OR
 Clearance = $0,25m$
 $= 0,25 \times 4$
 $= 1 \text{ mm}$

✓
✓
(2)
- 5.1.7
$$\text{module} = \frac{\text{PCD}}{\text{Teeth}}$$

$$\text{Teeth} = \frac{\text{PCD}}{m}$$

$$= \frac{104}{4}$$

$$= 26 \text{ teeth}$$

✓
✓
✓
(3)

5.2 Indexing

$$\begin{aligned}
 \text{Indexing} &= \frac{40}{n} && \checkmark \\
 &= \frac{40}{26} \\
 &= \frac{40}{26} \div \frac{2}{2} && \checkmark \\
 &= \frac{20}{13} \\
 &= 1 \frac{7}{13} \times \frac{3}{3} \\
 &= 1 \frac{21}{39} && \checkmark
 \end{aligned}$$

Indexing = 1 full turn of the crank and 21 holes on the 39 hole circle (4) ✓

5.3 Screw thread cutting

- Set up the work piece in the lathe and turn the part to be threaded to the major diameter of the thread. ✓
- Set the compound slide to the correct angle (30°) to the right and set the tool up accurately in the post. ✓
- Consult the index plate of the quick-change gearbox for 2 mm pitch and move the levers accordingly. ✓
- Start the lathe and set the cutting tool so that it just touches the work piece. Set graduated dials to zero (cross feed and compound slide) ✓
- Move cutting tool a short distance off end of work piece and feed compound slide say 0,06 mm inwards. ✓
- With lathe turning, engage half nuts at the correct line on the chasing dial, putting the first cut in progress. ✓
- Withdraw the cutting tool quickly and disengage the half-nut lever. Return the carriage to the starting point of the thread. ✓ **OR** Stop the machine, leave half nut engaged, back off slide past zero and return carriage to start position in reverse ✓
- Check with thread gauge to see if thread pitch is correct. ✓
- Repeat with successive cuts until thread is complete. (Remember to bring cross-feed collar back to zero for each cut) ✓
- Each successive cut is set by means of the compound slide. Check thread with ring gauge for correct fit. ✓

(10)
[30]

QUESTION 6: JOINING METHODS**6.1 MIG/MAGS welding equipment**

6.1.1 MIG/MAGS welding equipment ✓ (1)

6.1.2 **Labels**

A = Shielding gas cylinder ✓

B = Regulator ✓

C = Gas flow meter ✓

D = Continuous wire reel ✓

E = Welding gun ✓

F = Arc ✓

G = Earth clamp ✓

(7)

6.1.3 **Purpose**

Prevents oxygen ✓ to come in contact with the molten metal. ✓

(2)

6.2 Weld defects

6.2.1 **Defect: Slag inclusion**

Causes:

- Included angle is too narrow. ✓
- Rapid chilling. ✓
- Weld temperature is too low. ✓
- High viscosity of molten metal. ✓
- Slag from previous run weld not removed. ✓

(Any 2 x 1) (2)

6.2.2 **Defect: Undercutting**

Causes:

- Faulty electrode manipulation. ✓
- Current too high. ✓
- Arc length too long. ✓
- Speed of weld too fast. ✓

(Any 2 x 1) (2)

6.3 Welding defects**6.3.1 Defect: Lack of fusion****Preventions:**

- Adjust the electrode angle and prepare the V groove properly. ✓
- Weave must be sufficient to melt sides of the joint. ✓
- Proper current will allow fusion. ✓
- Adjust welding speed to ensure fusion. ✓


(Any 2 x 1) (2)**6.3.2 Defect: Weld craters****Preventions:**

- Use lower current. ✓
- Use proper welding technique. ✓
- Use correct electrode ✓

(Any 2 x 1) (2)**6.4 Dye penetration test**

- Clean the weld that needs to be tested. ✓
- The dye is sprayed onto the clean surface. ✓
- Allow the dye to penetrate the weld joint. ✓
- Excess dye is cleaned away with a cleaning agent. ✓
- Allow surface to dry thoroughly. ✓
- Spray a developer onto the surface to bring out the dye trapped in the crack. ✓
- The dye will show all the surface defects ✓

**(7)
[25]**

QUESTION 7: FORCES**7.1 Resultant**

$$\begin{aligned}
 7.1.1 \sum HC &= 4,7 - 3,1 \cos 50^\circ - 1,5 \cos 40^\circ \\
 &= 4,7 - 1,99 - 1,15 \\
 &= 1,56 \text{ kN}
 \end{aligned}$$

✓✓✓
✓

$$\begin{aligned}
 7.1.2 \sum VC &= 2,1 + 1,5 \sin 40^\circ - 3,1 \sin 50^\circ \\
 &= 2,1 + 0,96 - 2,37 \\
 &= 0,69 \text{ kN}
 \end{aligned}$$

✓✓✓
✓

7.1.3 Horizontal components	Magnitudes	7.1.4 Vertical components	Magnitudes
4,7 kN	4,7 kN ✓	2,1 kN	2,1 kN ✓
3,1 kN Cos50°	-1,99 kN ✓	1,5 kN Sin40°	0,96 kN ✓
1,5 kN Cos40°	-1,15 kN ✓	3,1 kN Sin50°	-2,37 kN ✓
TOTAL	1,56 kN ✓	TOTAL	0,69 kN ✓

$$E^2 = HC^2 + VC^2$$

$$E = \sqrt{1,56^2 + 0,69^2}$$


$$E = 1,71 \text{ kN}$$

$$\tan \phi = \frac{VC}{HC}$$

$$= \frac{0,69}{1,56}$$

$$\phi = 23,86^\circ$$

$$E = 1,71 \text{ kN at } 23,86^\circ \text{ north from east}$$



(15)

7.2 Stress and Strain

Forces

$$\text{Force} = \text{load} \times \text{gravity}$$

$$= 600 \times 10$$

$$= 6000 \text{ N} \quad \checkmark$$

$$\text{Area} = \frac{F^2}{4D}$$

$$= \frac{F \times 0,016^2}{4} \quad \checkmark$$

$$= 2,011 \times 10^{-4} \text{ m}^2 \quad \checkmark$$

$$\text{Stress} = \frac{\text{Force}}{\text{Area}}$$

$$= \frac{6000}{2,011 \times 10^{-4}}$$

$$= 29841551,83 \text{ Pa}$$

$$= 29,84 \text{ MPa}$$


(6)

7.3 One Pascal (1 Pa) is equal to one Newton force (1 N) \checkmark acting onto \checkmark an area of one square metre (1 m²) \checkmark

(3)

7.4 Reactions

Taking moments around A




$$(B \times 3,5) + (1400 \times 0,7) = (350 \times 6,7)2,65 + (1600 \times 6) \quad \checkmark$$

$$3,5B + 980 = 6214,25 + 9600 \quad \checkmark$$

$$\frac{3,5B}{3,5} = \frac{6214,25 + 9600 - 980}{3,5} \quad \checkmark$$

$$B = 4238,36 \text{ N}$$

Taking moments around B



$$(A \times 3,5) + (1600 \times 2,5) = (350 \times 6,7)0,85 + (1400 \times 4,2) \quad \checkmark$$

$$3,5A + 4000 = 1993,25 + 5880 \quad \checkmark$$

$$\frac{3,5A}{3,5} = \frac{1993,25 + 5880 - 4000}{3,5} \quad \checkmark$$

$$A = 1106,64 \text{ N}$$

(6)
[30]

QUESTION 8: MAINTENANCE**8.1 Routine maintenance.**

- Tear on the belt. ✓
- Misalignment of belt drive. ✓
- Overheating of components. ✓
- Belt slip. ✓
- Belt wear. ✓
- Pulley wear. ✓
- Financial loss due to the damage suffered. ✓
- Loss of valuable production time. ✓

(Any 2 x 1) (2)**8.2 Cutting fluid**

- To allow it to flow easily ✓
- Dissipate excess heat ✓
- Prevent excessive load on pump ✓

(Any 2 x 1) (2)**8.3 Flash point**

Is the lowest temperature at which the oil gives off a vapour which will ignite. ✓✓

(2)**8.4 'API'**

American Petroleum Institute ✓✓

(2)**8.5 Automatic transmission fluid**

- Transmit power in the torque convertor ✓
- Let hydraulic fluid transmit energy in order to move various parts such as the servo unit. ✓
- Acts as heat transfer medium to transfer heat within the transmission to outside and assist in cooling it down. ✓
- Acts as a lubricant for gears and bearings. ✓

(Any 2 x 1) (2)**8.6 Replace belt in a drill press**

- Machine should be switched off the locked out. ✓
- Tension on the belt to be released by loosening an adjusting screw or releasing the belt tensioner. ✓
- Remove the belt. ✓
- Replace with new belt of the correct type and size. ✓
- The belt should be re-tensioned and aligned. ✓

(5)**[15]**

QUESTION 9: SYSTEMS AND CONTROL**9.1 Gear drive****9.1.1 Rotational frequency of the electric motor:**

$$\frac{N_A}{N_D} = \frac{T_B \times T_D}{T_A \times T_C} \quad \checkmark$$

$$N_A = \frac{80 \times 63 \times 2}{30 \times 40} \quad \checkmark$$

$$N_A = \frac{10080}{1200} \quad \checkmark$$

$$N_A = 8,4 \text{ r/s} \quad \checkmark \checkmark$$

(5)

9.1.2 Speed ratio of gear train:

$$\text{Speed ratio} = \frac{\text{Input}}{\text{Output}}$$

$$= \frac{8,4}{2} \quad \checkmark$$

$$= 4,2 : 1 \quad \checkmark$$

OR

$$\text{Speed ratio} = \frac{\text{Driven teeth}}{\text{Driver teeth}}$$

$$= \frac{80}{30} \times \frac{63}{40} \quad \checkmark$$

$$= 4,2 : 1 \quad \checkmark$$

(2)

9.2 Belt drive**9.2.1 Diameter of the driven pulley**

$$N_1 \times D_1 = N_2 \times D_2$$

$$N_1 = \frac{N_2 \times D_2}{D_1} \quad \checkmark$$

$$= \frac{7,2 \times 600}{800} \quad \checkmark$$

$$= 5,4 \text{ r/s} \quad \checkmark$$

(3)

9.2.2 Power transmitted:

$$P = (T_1 - T_2) \frac{F}{D_n}$$

$$P = (300 - 120) \frac{F}{D_n} \times 0,6 \times 7,2$$

$$= 2442,90 \text{ Watt}$$

$$= 2,44 \text{ kW}$$

$$\frac{T_1}{T_2} = 2,5$$

$$T_2 = \frac{300}{2,5}$$

$$= 120 \text{ N}$$

OR

$$P = (T_1 - T_2) \frac{F}{D_n}$$

$$P = (300 - 120) \frac{F}{D_n} \times 0,8 \times 5,4$$

$$= 2442,90 \text{ Watt}$$

$$= 2,44 \text{ kW}$$

$$\frac{T_1}{T_2} = 2,5$$

$$T_2 = \frac{300}{2,5}$$

$$= 120 \text{ N}$$

(3)

9.3 The volume of gas can be changed by the altering of ...

- its pressure ✓
- its temperature ✓
- both its pressure and temperature ✓

(Any 2 x 1)

(2)

9.4 Definition of Boyle's law

The volume of a given mass ✓ of gas is inversely proportional to the pressure ✓ on it, if the temperature remains constant ✓

(3)

9.5 Hydraulics**9.5.1 Fluid pressure**

$$\begin{aligned}
 A_A &= \frac{F^2}{D^4} \\
 &= \frac{0,04^2}{4} \\
 &= 1,26 \times 10^{-3} \text{ m}^2 \quad \checkmark
 \end{aligned}$$

$$\begin{aligned}
 P_A &= \frac{F}{A_A} \\
 &= \frac{80}{1,26 \times 10^{-3}} \text{ Pa} \quad \checkmark \\
 &= 63661,98 \text{ Pa} \\
 &= 63,66 \text{ kPa} \quad \checkmark
 \end{aligned}$$

(3)

9.5.2 Diameter of piston B

$$\begin{aligned}
 P_B &= P_A \\
 P_B &= \frac{F_B}{A_B} \quad \checkmark
 \end{aligned}$$

$$\begin{aligned}
 A_B &= \frac{F_B}{P_B} \\
 A_B &= \frac{320}{63492,06}
 \end{aligned}$$

$$A_B = 5,04 \times 10^{-3} \quad \checkmark$$

$$A = \frac{F^2}{D^4} \quad \checkmark$$

$$\begin{aligned}
 D_B &= \sqrt{\frac{A_B \times 4}{F}} \\
 &= \sqrt{\frac{5,04 \times 10^{-3} \times 4}{F}} \\
 &= 0,08 \text{ m} \\
 &= 80 \text{ mm} \quad \checkmark
 \end{aligned}$$

(4)
[25]

QUESTION 10: TURBINES

- 10.1 **Water turbine blades**
To supply water pressure ✓ to the turbine ✓ (2)
- 10.2 **Reverse flow**
• Deriaz ✓
• Francis ✓ (2)
- 10.3 **Supercharger**
• Roots ✓
• Twin screw ✓
• Centrifugal ✓
• Vane ✓
(Any 2 x 1) (2)
- 10.4 **Turbocharger**
• Exhaust gases drive the turbine ✓
• The turbine drives a compressor via a common shaft ✓
• The compressor forces ✓ compressed air above atmospheric pressure into the cylinder ✓
• Exhaust gases leave system through the exhaust pipe ✓ (5)
- 10.5 **Supercharger over turbocharger**
• Do not suffer lag ✓
• More efficient at low revolution per minute. ✓
• Does not require extensive exhaust modification. ✓
• No special shutdown procedure is required. ✓
(Any 2 x 1) (2)
- 10.6 **Lag**
Lag is the delay ✓ between pressing the accelerator pedal ✓ and feeling the pressure building up. ✓ (3)
- 10.7 **Supercharger drive**
• Belt drive ✓
• Gear drive ✓
• Chain drive ✓
(Any 2 x 1) (2)

10.8 Gas turbine disadvantages

- Cost is much greater than for a similar-sized reciprocating engine since the materials must be stronger and more heat resistant. ✓
- Manufacturing operations are also more complex. ✓
- Usually less efficient than reciprocating engines, especially at idling speed. ✓
- Delayed response to changes in power settings. ✓

(Any 2 x 1) (2)
[20]

TOTAL: 200