

You have Downloaded, yet Another Great Resource to assist you with your Studies ③

Thank You for Supporting SA Exam Papers

Your Leading Past Year Exam Paper Resource Portal

Visit us @ www.saexampapers.co.za







## NATIONAL SENIOR CERTIFICATE

# **GRADE 12**

# **SEPTEMBER 2020**

# MECHANICAL TECHNOLOGY: FITTING AND MACHINING MARKING GUIDELINE

MARKS: 200

This marking guideline consists of 18 pages.

### QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)

1.1	C✓	(1)
1.2	B✓	(1)
1.3	C✓	(1)
1.4	A✓	(1)
1.5	B✓	(1)
1.6	C✓	(1) <b>[6]</b>

### **QUESTION 2: SAFETY (GENERIC)**

2.1	Gas	welding	(PPE)
-----	-----	---------	-------

- Eye protection ✓
- Overall / leather apron ✓
- Safety boots ✓
- Gloves ✓

(Any 2 x 1) (2)

# 2.2 Safety rules that must be followed whilst the surface grinder is in operation:

- Make sure that the sparks are of no danger to co-workers.  $\checkmark$
- Do not force the material onto the grinding wheel.  $\checkmark$
- Do not plunge grind. ✓
- Bring the material slowly into contact with the grinding wheel. ✓
- Never clean or adjust the machine whilst it is in motion. ✓
- Use cutting fluid. ✓
- Know where the emergency stop is located. ✓
- Stop machine before any adjustment ✓
- Keep tools clear from moving parts. ✓ (Any 2 x 1) (2)

2.3	<b>Completing a task on any machine</b> Switch the machine off. $\checkmark$	(1)
2.4	TWO safety precautions before switching the angle grinder on	
	<ul> <li>Make sure that there are no cracks or chips on the disc. ✓</li> <li>Make sure that the emery disc that is fitted is rated above the revolutions at which it is turned by the motor. ✓</li> <li>Make sure that the space between the tool rest and the emery disc does not exceed 3 mm. ✓</li> <li>Ensure that guards are in place. ✓</li> <li>When switching on the machine, do not stand in front of it, until it reaches its full speed. ✓</li> <li>Do not force or bump the work piece against the emery disc. ✓</li> <li>Grind only on the front surface of the wheel, not the sides. ✓</li> <li>All grinding machines must have a sign indicating the revolutions at which the spindle rotates. ✓</li> </ul>	(2)
2.5	<ul> <li>Importance of a welding helmet</li> <li>To protect your eyes and face from ultra-violet rays and radiation √</li> </ul>	(1)
2.6	<ul> <li>Types of workshop layouts:</li> <li>Process layout ✓</li> <li>Product layout ✓</li> </ul>	(2) <b>[10]</b>

### QUESTION 3: MATERIALS (GENERIC)

### 3.1

	DIFFERENT TYPES OF TESTS							
MATERIALS	Sound	Filing	Bend					
Cast iron	Very dull sound ✓	Easy ✓	Cannot bend ✓/ Snaps/breaks ✓/ Fractures easily ✓					
Mild steel	Medium metallic sound ✓	Easy ✓	Bends easily √					

(6)

(2)

#### 3.2 Heat treatment process

٠	Is the heating and cooling of metals in their solid state so as to	
	change their properties ✓	(1)

#### 3.3 Hardness factors:

- Workpiece size ✓ •
- Quenching rate ✓ •
- Carbon content ✓ (Any 2 x 1) •

#### 3.4 Heat treatment processes:

#### 3.4.1 Tempering

- Is a process applied to steel and it relieves the strains induced during the hardening process  $\checkmark$
- Decreases the degree of hardness ✓
- Increases toughness ✓
- Reduces brittleness ✓
- Gives steel fine grain structure ✓ (Any 2 x 1) (2)

### 3.4.2 Annealing

- Relieves internal stress ✓
- Softens the metal ✓
- Makes metal ductile ✓
- Refines the grain structure ✓
- Reduces brittleness ✓ (Any 2 x 1)
- 3.5 Hardness of steel depends upon
  - Carbon content ✓

(1) [14]

(2)

### QUESTION 4: MULTIPLE-CHOICE QUESTIONS (SPECIFIC)

4.1	B✓	(1)
4.2	D✓	(1)
4.3	D✓	(1)
4.4	A✓	(1)
4.5	A✓	(1)
4.6	B✓	(1)
4.7	A✓	(1)
4.8	B✓	(1)
4.9	B✓	(1)
4.10	A✓	(1)
4.11	B✓	(1)
4.12	B✓	(1)
4.13	C ✓	(1)
4.14	B✓	(1) <b>[14]</b>

(1)

### QUESTION 5: TERMINOLOGY (LATHE AND MILLING MACHINE) (SPECIFIC)

### 5.1 Lathe components

5

.1.1	•	Chuck is a lathe component used to mount and hold the	
		workpiece at one end. 🗸	(1)

- 5.1.2 Tool post is securely clamped to the compound slide and is used to support and fasten the cutting tool in the proper position for cutting action. ✓ (1)
- 5.1.3 Compound slide is situated on top of the cross slide and is used for turning operations such as taper turning and thread cutting. ✓

### 5.2 Milling Cutters Classes

5.2.1	Arbor cutters ✓	
	Examples: plain cutter, side cutter, staggered-tooth cutter,	
	slitting-saw cutter, angular cutter, profile/form cutters, side-and-	
	face cutter, helical cutter ✓	(2)

5.2.2 Shank cutters ✓
 Examples: end mill; shell end mill; T-slot cutter and Woodruff keyseat cutter ✓
 (2)

### 5.3 Taper-turning calculations

 $\Theta = 8,5^{\circ}$   $\theta/2 = 4,25^{\circ}\checkmark$ Tan  $\theta/2 = (D - d)/2L\checkmark$ Tan 4,25 x 2 x 250 = (55-d)  $\checkmark$ d = 17,84 mm d = 18 mm  $\checkmark$ 

### 5.4 **Dividing head components**

- A Index plate ✓
- B Index crank ✓
- C Sector arms ✓
- D Single-start worm ✓
- E Worm wheel/gear ✓

### 5.5 Lead calculations

Lead = No. of starts x pitch

- = 3 x 1,75 mm ✓
  - = 5,25 mm ✓

(2) [**18**]

(4)

(5)

### QUESTION 6: TERMINOLOGY (INDEXING) (SPECIFIC)

### 6.1 Gear calculations:

- 6.1.1 Dividing head: it breaks up the circumference of a circular workpiece into a number of equal parts. It is mounted between centers in cunjunction with the tailstock; or it can be fitted with a chuck for direct mounting of work. ✓
- 6.1.2 Index plate: to enable one revolution of the crank to be further subdivided into fractions of a revolution, especially where the fraction is the factor of 40. ✓
- 6.1.3 Sector arm: to enable indexing where fractions of turns are required, so that it can be adjusted to any angle that would contain a specific number of holes. ✓

6.2 **Procedure to cut external metric V-screw thread using compound slide method.** 

- Set up the workpiece in the centre lathe and turn the part to be threaded to the required diameter of the thread. ✓
- Set the compound slide to 30° to the left of the centre line of that cross-slide and accurately set up the cutting tool in the tool post. ✓
- Consult the index plate of the quick-change gear box and shift the levers accordingly for the necessary pitch of the screw thread. ✓
- Start the centre lathe and set the cutting tool at touching point on the workpiece. ✓
- Move the cutting tool a short distance off, to clear the end of the workpiece and feed the compound slide 0,05 mm inwards. ✓
- With the centre lathe revolving, engage the half nuts at the correct line on the threading dial, putting the first cut of the screw thread in progress. ✓
- Stop the centre lathe and check the screw thread pitch with a screw thread pitch gauge. ✓ (Any 5 x 1) (5)
- 6.3 **Definition of Indexing:** It is the process of evenly dividing the circumference of a circular work piece into equally spaced divisions, such as in cutting gear teeth, cutting splines, milling grooves in the reamers and taps. ✓

### 6.4 Milling methods

- Up-cut milling ✓
- Down-cut milling ✓

(2)

(1)

(1)

(1)

(1)

#### 6.5 **Differential indexing**

	Hole circles										
Side 1	Side 1 24 25 28 30 34 37 38 39 41 42 43										
Side 2	46	47	49	51	53	54	57	58	59	62	66

Standard change gears										
24 x 2	28	32	40	44	48	56	64	72	86	100

#### Indexing required 6.5.1

Indexing = 
$$\frac{40}{A}$$
  $\checkmark$   
= 40/120  
=  $\frac{1}{3} \times \frac{22}{22} \checkmark$   
= 22/66

Indexing is 22 holes in a 66-hole circle.  $\checkmark$ 

(3)

#### Change of gears 6.5.2

Gear ratio : 
$$\frac{Driven}{Driven} = \frac{A-N}{A} \ge \frac{40}{1} \checkmark$$
$$= \frac{120-113}{120} \ge 40 \checkmark$$
$$= +\frac{7}{3} \ge \frac{8}{8} \checkmark$$
$$= 56/24 \checkmark$$

The driver gear has 56 teeth.	
The driven gear has 24 teeth. $\checkmark$	(5)

6.5.3 The direction of motion is clockwise. The crank handle will turn the same direction as the index plate √ (1)

### 6.6 **Dove tail calculations:**

Find the difference of distance over the rollers (L):

 $L = (M - R) - (m - r) \checkmark$ = (127,64 - 25) - (100,32 - 15) \sqrt{102,64} - 85,32 L = 17,32 mm \sqrt{102,64}

For the angle θ Tan θ/2 = (R − r) / L ✓ = 10/17,32 ✓

$$\Theta = 30 \times 2$$
  

$$\Theta = 60^{\circ} \checkmark$$
(6)

### 6.7 Constraints to balancing

- Requires specialised machinery ✓
- Difficult to ascertain the exact point of unbalance  $\checkmark$
- Requires accurate removal or addition of material's weight to the object. ✓
- Can lead to interference with parts of the machine when weights are added to parts ✓ (Any 2 x 1) (2)

[28]

MECHANICAL TECHNOLOGY: FITTING AND MACHINING (EC/SEPTEMBER 2020)

### **QUESTION 7: TOOLS AND EQUIPMENT (SPECIFIC)**

#### 7.1 Hardness testers:

7.1.1

Brinell hardness tester



7.1.2 Rockwell hardness tester



#### 7.2 Hardness measure of a metal

- Resistance to penetration ✓ •
- Elastic hardness ✓ •
- Resistance to abrasion ✓ (3)

### 7.3 Screw-thread micrometres

 $6 + 0.5 + 0.3 = 6.80 \text{ mm} \checkmark \checkmark$ 

### 7.4 Micrometre reading 41,25 mm





(2)

### **QUESTION 8: FORCES (SPECIFIC)**

#### **Resultant force calculations:** 8.1



- Xcom = 80 cos 30 40 cos 75 70 cos 25 50 cos 40 √√ = 80,0686 N ✓
- $Y_{com} = 50 \sin 40 80 \sin 30 70 \sin 25 40 \sin 75$  $\checkmark\checkmark$ = -16,91 N ✓

R = 
$$\sqrt{(X^2 + Y^2)}$$
   
R = 81,836 N  $\checkmark$ 

Equilibrant = Resultant BUT IN THE OPPOSITE DIRECTION ✓

Equilibrant = 81,836 N at 168,075° ✓

#### 8.2 **Moments**

Converting the UDL to point lolad 1 x 10 = 10 kN @ 5 mm from eft hand end  $\checkmark$ 

### Calculation of the reactions. Taking moments:

 $R_D \ge 20 = (5 \ge 5) + (10 \ge 30) + (20 \ge 15) \checkmark$ = 31,25 kN ✓  $(Ra \times 20) + (10 \times 10) = (20 \times 5) + (5 \times 15) \checkmark$ = 3,75 kN ✓

(5)

(12)

13

(4)

- 8.3 Stress calculations:
  - 8.3.1 Tensile Stress Calculations
    - F = 10 kN; d = 20 mm: L = 2 m : E = 200 PGa  $\delta = \frac{F}{A}$   $A = \pi r^2$ A =  $\pi \times 0.01^2 \checkmark$ A = 3.141 x 10^-4 m<sup>2</sup>  $\checkmark$   $\delta = \frac{F}{A}$ = 10 000/3.141 x 10 ^-4 $\checkmark$ = 318.31 x 10<sup>6</sup> Pa = 318.31 MPa $\checkmark$

8.3.2 **The change in length calculations**.  $\Delta L = ?; E = 200 \text{ GPa}; F = 10 \text{ kN}; L = 2 \text{ m}; 6 = 318,31 \text{ MPa}$ 

$$\Delta L = \frac{S \times L}{E} \checkmark$$
  
= 318,31 × 10<sup>6</sup> × 2) / 200 × 10<sup>9</sup>  $\checkmark \checkmark$   
= 0,318 mm  $\checkmark$  (4)

8.4 Stress/Strain diagram:



### 8.5 FOS stands for Factor **OR** Safety or Safety Factor. $\checkmark$ (1)

8.6 Young's modulus states that stress in metal is directly proportional to the strain it causes, provided the limit of proportionality is not exceeded. ✓ (1)

[33]

(6)

### MECHANICAL TECHNOLOGY: FITTING AND MACHINING (EC/SEPTEMBER 2020)

### **QUESTION 9: MAINTENANCE (SPECIFIC)**

9.1	Purpose of composites:							
	9.1.1	Bakelite can be used in disc brake cylinders, saucepan handles, distributor rotors, electrical plugs and switches, and parts for electrical irons. $\checkmark$	(2)					
	9.1.2	Fibre glass is used as a surface covering, woven cloth, wearing fibres, plastic covers and stuffing for pillow. $\checkmark\checkmark$	(2)					
	9.1.3	Carbon fibre is used for sport equipment like tennis, squash and badminton racquets, racing bicycle frames, construction skis, surfboards and boat masts, compressor blades for jet engines. $\checkmark \checkmark$	(2)					
9.2	<ul> <li>Reaso</li> <li>It pr</li> <li>It pr</li> <li>cutt</li> <li>It with</li> <li>It flut</li> <li>It flut</li> </ul>	Ins for using cutting fluid when working on the centre lathe: rolongs the life of a cutting tool. $\checkmark$ revents the shavings or metal chips from sticking and fusing to the ing tool. $\checkmark$ ill carry away the heat generated by the turning process. ushes away shavings/metal chips. $\checkmark$ hproves the quality of the finish of the turned surface. (Any 1 x 1)	(1)					
9.3	Mecha • Gea • Cha • Belt	ar drives: ar drives ✓ ain drives ✓ c drives ✓	(3)					
9.4	Reaso • It is • It is • It ca	ns for the use of carbon fibre: light in weight ✓ tougher and stronger ✓ an be bent to any shape when heated above 150 °C ✓ (Any 2 x 1)	(2)					

COMPOSITE	PROPERTY	USES
9.5.1 PVC	<ul> <li>Durable</li> <li>Very versatile</li> <li>High load bearing strength</li> <li>High chemical resistance</li> <li>Very low co-efficient of friction (Any 1 x 1)</li> </ul>	<ul> <li>Bank credit cards</li> <li>Shoe soles</li> <li>Wallpaper</li> <li>Floor tiles</li> <li>Drip bags</li> <li>Cooking oil bottles (Any 1 x 1)</li> </ul>
9.5.2 Vesconite	<ul> <li>Withstands high temperatures</li> <li>Self-lubrication</li> <li>Resistant to water, grease, heat and corrosion</li> <li>Good machinability (Any 1 x 1)</li> </ul>	<ul> <li>Orthopaedic and prosthetic appliances</li> <li>Hearing aids</li> <li>Upholstery (Any 1 x 1)</li> </ul>
9.5.3 Nylon	- Toughness - Hard-wearing - Cheap - Needs little maintenance (Any 1 x 1)	<ul> <li>Bushes, toys, curtain hooks</li> <li>Gears</li> <li>Pulleys (Any 1 x 1)</li> </ul>

### 9.5 **ONE property and ONE use of each composite**

(6) **[18]** 

### QUESTION 10: JOINING METHODS (SPECIFIC)

10.1	Square thread calculations:	
	10.1.1 PCD = T x m = 60 x 4 = 240 mm $\checkmark \checkmark$	(2)
	10.1.2 Add = Module = 4	(2)
	10.1.3 Clearance = 0,157 x m = 0,628 mm $\checkmark \checkmark$	(2)
	10.1.4 Ded = 1,157 x m = 4,628 mm $\checkmark \checkmark$	(2)
	10.1.5 OD = PCD + 2 x m = 248 mm $\checkmark \checkmark$	(2)
10.2	Left-hand square screw-thread: A – Leading angle ✓ B – Following or Trailing Angle ✓ C – Clearance ✓ D – Helix angle ✓	(4)
10.3	A multi-start thread allows for faster travel or movement and is more efficient as it loses less power to friction compared to single-start thread. $\checkmark \checkmark$	(2)
10.4	Screw-thread fit is a combination of allowances and tolerances and a measure of tightness or looseness between the bolt and nut. $\checkmark\checkmark$	(2) <b>[18]</b>

### **QUESTION 11: SYSTEMS AND CONTROL (SPECIFIC)**

11.1 Gear drives work on the principle that the turning motion of one gear be transferred to another gear if the gears are mounted close so that they mesh or engage. ✓✓

### 11.2 Hydraulic system calculations:

### 11.2.1 Calculate the force applied on Piston A.

da = 30 mm; Db = 130 mm; M = 2 000 kg Weight Calculation (W) W = m x g  $\checkmark$ = 2 000 x 10 = 20 Kn  $\checkmark$ 

11.2.2  $A = \pi (r)^2$ =  $\pi x 0,065^2 \checkmark$ = 0,0133 m<sup>2</sup>  $\checkmark$ 

$$P = \frac{F}{A}$$
  
= 20 000/0,0133 ✓  
= 1,507 MPa ✓

11.2.3 
$$A = \pi Da^{2}/4$$
  
=  $\pi (0.03)^{2}/4$   $\checkmark$ 

$$= \pi (0,03)^{2/4} \qquad \checkmark$$
  
= 7,0686 x10^{-4} m^2  $\checkmark$   
F = P x A  
= 1,507 x 10<sup>-6</sup> x 7,068 x 10^{-4}  $\checkmark$   
Force = 1065,235 N  $\checkmark$  (4)

# 11.3 Velocity ratio is defined as the ratio of a distance through which any part of a machine moves, to that which the driving part moves during the same time. $\checkmark$

### 11.4 Belt drive calculations: Nmotor x Dmotor = Nblade x Dblade ✓

135 x 1 200 = 395 x D<sub>blade</sub> ✓

Dblade = 410,127 rpm ✓

(2)

(2)

(4)

(3)

(2)

11.5 **Pneumatic drives:**  Vehicle painting ✓ Air brakes ✓ Opening and closing doors ✓ Dismantling vehicle tire ✓ (Any 3 x 1) (3)11.6 Simple gear calculations: TA = 56 teeth; NA = 700 rpm  $\mathsf{TB} = \frac{TA \times NA}{NB} \checkmark$ 11.6.1 = (56 x 700)/ 980 ✓✓ = 40 teeth  $\checkmark$ (3) $Nc = \frac{NB \times TB}{Tc} \checkmark$ 11.6.2 = (40 x 980)/ 64 ✓ = 612,5 rpm ✓ (3)11.6.3 Driven gear will rotate anti-clockwise ✓ (1)[28] TOTAL: 200